DPM 5417

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Leeder Chemicals, Inc. s	pecialty Chemicals Division of Reliance Universal Inc.
16961 Knott Avenue • La Mirada, California	a 90638 • (213) 583-9761
Emergency Phone No. (714) 739-2821	Date May 24, 1984
	SECTION I
CHEMICAL NAME AND SYNONYMS Lube Stick CHEMICAL FAMILY	TRADE NAME AND SYNONYMS Leeder 300-Z FORMULA
Alcohols	Alcohols

SECTION II - HAZARDOUS INGREDIENTS						
PAINTS, PRESERVA	ATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	Carlino'	1		BASE METAL		,
CATALYST	CTIVED S	<		ALLOYS		
VEHICLE	(ε- Ch.)		8	METALLIC COATINGS		
SOLVENTS	E DECS 9 136			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES	15 000 m. 200 m.		19	OTHERS		
OTHERS	\ (6				
	HAZARDOUS MIXTURES	OF (OTHER LIC	DUIDS, SOLIDS, OR GASES	%	TLV (Units)
This product is considered non-hazardous under current Department of						
Labor definitions.						

SECTION III - PHYSICAL DATA				
BOILING POINT (°F.) Not applicable.	SPECIFIC GRAVITY (H2O=1)	Not applica	ble.	
VAPOR PRESSURE (mm Hg.) Not applicabl	PERCENT, VOLATILE BY VOLUME (%)	Not applica	ble:	
VAPOR DENSITY (AIR=1) Not applicable	EVAPORATION RATE	Not applica	ble.	
SOLUBILITY IN WATER Non-soluble.				
APPEARANCE AND ODOR Solid, wax-wi	nite.			

FLASH POINT (Method used) Not applicable.	FLAMMABLE LIMITS	Lel	Uel
Not applicable.	Unknown.		L
EXTINGUISHING MEDIA			
Foam, carbon dioxide or dry ch	emical.		
SPECIAL FIRE FIGHTING PROCEDURES			
Use self-contained breathing a	pparatus.		
•			
UNUSUAL FIRE AND EXPLOSION HAZARDS	,		

	SECTION V - HEALTH HAZARD DATA						
THRESHOLD LIMIT	VALUE						
Not applicable. EFFECTS OF OVEREXPOSURE This material is considered non-toxic.							
This mate	rial	is consi	dered	non-	-toxic		
EMERGENCY AND F	IRST A	ID PROCEDU	JRES				
							And the second s
	<u>.</u>	· · · · · · · · · · · · · · · · · · ·				1/4/	
		73			 		
			SECTI	ON \	/I - R	EACTIVITY DA	TA
STABILITY	UNST	ABLE		CO	NOTION	is to AVOID	trong ovidizare
	STAB	LE	- X	- A	Avoid contact with strong oxidizers.		
INCOMPATABILITY	(Materi	als to avoid)		_ 		,	
Strong ox HAZARDOUS DECO	MPOSI"	TION PRODU	CTS				
None.		MAY OCCU	R		<u> </u>	CONDITIONS TO A	AVOID
POLYMERIZATION		WILL NOT	OCCUR		Х		
						<u> </u>	
		SECT	ION VI	11 - 3	SPILL	OR LEAK PROC	EDURES
STEPS TO BE TAKE Sweep up.						SPILLED	
oncep_up.						,	
WASTE DISPOSAL N	иетно 11 1	ocal code	s gove	erno	ng pro	per waste dis	posal.
		· · · · · · · · · · · · · · · · · · ·				10	·
				SPE	CIAL P	ROTECTION IN	FORMATION
RESPIRATORY PRO None requ	ired	•	• •				
VENTILATION		AL EXHAUST					SPECIAL
	MECHANICAL (General) Adequate.				OTHER		
PROTECTIVE GLOVES None required. None required.							
OTHER PROTECTIVE EQUIPMENT None required.							
							1010
PRECAUTIONS TO I	BE TAL					CIAL PRECAUT	IUNS
Do not st	ore	with stro	ong oxi	idiz	ing ag	gents.	
OTHER PRECAUTIO	ME				· · · · · · · · · · · · · · · · · · ·		
Do not ta		nternally	7.•				

PAGE (2)

Form OSHA-20 Rev. May 72